

TruVision/UltraSync 1080p Wi-Fi Bullet and Desktop Cameras Firmware V1.1 FP4 Release Notes

P/N 1073530-EN • REV A • ISS 12JUL17

Introduction

This is the TruVision/UltraSync 1080p Wi-Fi Bullet and Desktop Cameras Firmware V1.1 FP4 Release Notes. For the latest information on the product, please visit:

Americas: <http://www.interlogix.com/videoupgrades>

EMEA: www.firesecurityproducts.com

Australia: www.utcfs.com.au

Supported cameras

Model No.	Description
TVQ-8101	TruVision 1080p, NTSC/PAL, Wi-Fi, Indoor Desktop, White, True D/N, H.264, PSIA/ONVIF/CGI, Audio, 10 m IR, 2.0 mm @F2.0, PoE/12 VDC
TVB-8101	TruVision 1080p, NTSC/PAL, Wi-Fi, Outdoor Bullet, Gray, True D/N, H.264, PSIA/ONVIF/CGI, 20 m IR, 4 mm fixed Lens, PoE/12 VDC
RS-3230	UltraSync Compatible, 1080p, NTSC/PAL, Wi-Fi, Indoor Desktop, White, True D/N, H.264, PSIA/ONVIF/CGI, Audio, 10 m IR, 2.0 mm @F2.0, PoE/12 VDC, US/UK/EU/AU Power Supply and 16 GB Micro SD card included
RS-3231	UltraConnect Compatible, 1080p, NTSC/PAL, Wi-Fi, Indoor Desktop, White, True D/N, H.264, PSIA/ONVIF/CGI, Audio, 10 m IR, 2.0 mm @F2.0, PoE/12 VDC, US/UK/EU/AU Power Supply and 16 GB Micro SD card included
RS-3250	UltraSync Compatible, 1080p NTSC/PAL, Wi-Fi, Outdoor Bullet, Gray, True D/N, H.264, PSIA/ONVIF/CGI, 20 m IR, 4 mm fixed lens, PoE/12 VDC, US/UK/EU/AU Power Supply and 16 GB Micro SD card included

Model No.	Description
RS-3251	UltraConnect Compatible, 1080p NTSC/PAL, Wi-Fi, Outdoor Bullet, Gray, True D/N, H.264, PSIA/ONVIF/CGI, 20 m IR, 4 mm fixed lens, PoE/12 VDC, US/UK/EU/AU Power Supply and 16 GB Micro SD card included

Issues resolved with Firmware V1.1 FP4

1. The password activation feature (permits use of the camera setup wizard in the UltraSync mobile app to set up the camera's password) was added.
2. UltraSync mobile app video search was optimized.
3. Fixed a Safari browser issue.
4. Changed the SMTP connection timeout to 10 seconds to support additional email service.
5. Fixed a WEP vulnerability issue.
6. Video standard support via the UltraSync mobile app was added.
7. Local network domain name support was added.
8. Encrypted XML password reset support was added.
9. XML notification time format was changed.
10. The UPnP default setting was changed to disabled.
11. The DDNS default setting was changed to disabled.
12. The default image mode was changed to custom-24h.

Contacting support

For help installing, operating, maintaining, and troubleshooting this product, refer to this document and any other documentation provided. If you still have questions, contact us during business hours (Monday through Friday, excluding holidays).

Note: Please be ready at the equipment before calling.

North America

T +1 855.286.8889

E techsupport@interlogix.com

W www.interlogix.com/support

Europe, Middle East, and Africa

W Select *Support/Contact Us* at www.firesecurityproducts.com

Australia

E security.tech.support@interlogix.com.au

W www.utcfs.com.au
