

TruVision NVR 22 Firmware 2.3b Release Notes

P/N 1073626-EN • REV B • ISS 21MAR19

Introduction

This is the TruVision NVR 22 Firmware 2.3b Release Notes document with additional information not covered in the user manual. For the latest information on the TruVision NVR 22 (TVN 22), please visit:

Americas: www.interlogix.com/videoupgrades

EMEA: www.firesecurityproducts.com

Australia: www.utcfs.com.au

Overview

The TVN 22 (P/S) series is a Network Video Recorder capable of supporting H.264 and H.265 IP cameras and is available in various channel and storage configurations. Firmware 2.3b contains a bug fix.

Bug fix

- An issue with DST (Daylight Savings Time) that was found in FW 2.3a has been resolved.

That issue caused the recorder to stop recording after the time change.

Contacting support

For help installing, operating, maintaining, and troubleshooting this product, refer to this document and any other documentation provided. If you still have questions, contact us during business hours (Monday through Friday, excluding holidays).

Note: Please be ready at the equipment before calling.

Table 1: Technical support

North America

T +1 855.286.8889

E techsupport@interlogix.com

W www.interlogix.com/customer-support

Europe, Middle East, and Africa

W Select *Support/Contact Us* at www.firesecurityproducts.com

Australia

E security.tech.support@interlogix.com.au

W www.utcfs.com.au
